


**LEACHATE COLLECTION WELLS
OM&M MONITORING AND BAILING DATA SHEET
WASTE DISPOSAL, INC. SUPERFUND SITE**

DATE: September 13, 2007


TECHNICIAN NAME: Refugio D. Gutierrez

TECHNICIAN SIGNATURE 

WELL ID	BOTTOM OF WELL AFTER CONSTRUCT-ED [TOTAL DEPTH] (ft)	MEASURED BOTTOM OF WELL [TOTAL DEPTH] (ft)	GAUGING TIME		DEPTH TO LIQUID (ft)						HEIGHT OF LIQUID COLUMN (ft)		VOLUME OF LIQUID REMOVED (gallons)	COMMENTS
			Start	Finish	Start			Finish			Start	Finish		
					1 st Rdg.	2nd Rdg.	3 rd Rdg.	1 st Rdg.	2nd Rdg.	3 rd Rdg.				
LC-1	22.25	22.25	0320	0328	20.05	20.05	20.05	21.75	21.75	21.75				
LC-2	21.90	21.90	0340	0343	13.35	13.35	13.35	21.15	21.15	21.15				
LC-3	22.20													
LC-4	21.90	21.90	0402	0414	13.48	13.48	13.48	20.95	20.95	20.95				

W:\InterimOpMain+Mon\LeachateCollectionWells\WorkPlan+FieldForms\February2007\Feb107LC-WellsM&B(YF1).doc

**LEACHATE COLLECTION WELLS
OM&M INSPECTION SHEET
WASTE DISPOSAL, INC. SUPERFUND SITE**

INSPECTOR'S NAME	INSPECTOR'S SIGNATURE	INSPECTION TIME	INSPECTION DATE
Refugio D. Geronimo			September 13, 2007

ITEM OF POTENTIAL CONCERN	CONDITIONS OBSERVED				COMMENTS	CHECK (✓) BELOW WHEN COMPLETED
	WELL ID LC-1	WELL ID LC-2	WELL ID LC-3	WELL ID LC-4		
Wellhead (well box, cover, gasket, concrete)	ok	ok	ok	ok		✓✓✓✓
Well Casing and Cap/Plug	ok	ok	ok	ok		✓✓✓✓
Liquid Present in Well Box	ok	ok		ok		✓✓✓✓
Other:						
Other:						
Other:						

W:\InterimOpMain+Mon\LeachateCollectionWells\WorkPlan+FieldForms\February2007\Feb507LC-WellsInspection(YF).doc

